



July 22, 2020

Mr. Stanley Carpenter
Colonial Pipeline Company
1089 Kings Highway
West Deptford, NJ 08086

RE: REQUEST FOR ADDITIONAL INFORMATION
Case No. 2018-0459-HA
Colonial Pipeline Bel Air Pumping Station
2942 Charles Street, Forest Hill
Harford County, Maryland

Dear Mr. Carpenter:

The Maryland Department of the Environment's (MDE) Oil Control Program (OCP) completed a review of the case file for the above-referenced property, including the *Quarterly Monitoring Report November 2019 – January 2020*, dated March 2020. OCP personnel were on site in December 2019 to oversee the installation of two additional monitoring wells, MW-12 and MW-13. It was brought to OCP's attention that there is an abandoned pipeline in the vicinity, on the east side of the entrance road. This abandoned line is outside the excavation where the active pipelines were installed. The OCP reviewed the available information for this site and found reference to a 30-inch abandoned line and its approximate location is depicted on the enclosed Site Plan.

Based on the available information reviewed for this case, MDE requires Colonial Pipeline to submit the following information for our review **no later than August 19, 2020**:

1. Submit a report to include the following information: when was this abandoned pipeline last used; when and why was it abandoned; the horizontal length/extent of the abandoned pipeline as it extends past the confines of the enclosed map; what methods were used to abandon the pipeline; how is the abandoned pipeline monitored; any subsurface investigative work performed in the area of the abandoned pipeline; and any other pertinent information.
2. Include an aerial map that depicts the full extent of the abandoned pipeline's location on and off the Bel Air Pumping Station property.

Mr. Stanley Carpenter
Case No. 2018-0459-HA
Page - 2 -

When submitting documentation to OCP, provide three hard copies and one electronic copy.
If you have any questions, please contact Ms. Lindley Campbell at 410-537-3387
(lindley.campbell1@maryland.gov) or me at 410-537-3499 (susan.bull@maryland.gov).

Sincerely,

A handwritten signature in black ink, appearing to read "Susan Bull". The signature is fluid and cursive, with the first name "Susan" and the last name "Bull" clearly distinguishable.

Susan R. Bull, Eastern Region Supervisor
Remediation Division
Oil Control Program

Enclosure: Colonial Site Map Figure 5, Belair Pumping Station

cc: Mr. David Kudla, Project Manager, TRC Environmental Corporation
Mr. John Resline, Acting Director, Environmental Health, Harford County Health Department
Mr. Andrew B. Miller, Chief, Remediation Division, Oil Control Program
Mr. Christopher H. Ralston, Program Manager, Oil Control Program

Mr. Stanley Carpenter
Case No. 2018-0459-HA
Page - 3 -

Mr David Kudla
TRC Environmental Corp
1801 Market St Suite 1380
Philadelphia PA 19103